

ULTRAVIOLETTE AUTOMOTIVE PRIVATE LIMITED

PROJECT DELIVERY REPORT PO -UV/PO/05757

For Enquiry keerthan.hk@emuski.com

Contact: +918660911980 | Website: www.emuski.com

EMUSKI

DELIVERY REPORT

TABLE OF CONTENT

| CHAPTER NO | TITLE | | | |
|---------------|--------------------------------|---|--|--|
| | Project Details | | | |
| 1 0 1 | Part details- VQ240210_0.B | 4 | | |
| | Manufacturing Process Plan | 4 | | |
| | Raw Material Inspection Report | 5 | | |
| 2.3 | 2D Drawing | 6 | | |
| | Final Inspection Report | 7 | | |
| 2.4 | Dock Audit Check List | 8 | | |
| 2.5 | Product Images | 9 | | |
| 3 | Key Learnings | 9 | | |

EMUSKI

DELIVERY REPORT

| S.no | Description | Value |
|------|------------------------------|-------|
| 1 | Customer Name | |
| 2 | Address | |
| 3 | Buyer Name | |
| 4 | Email id | |
| 5 | Contact Number | |
| 6 | Order type | |
| 7 | Purchase Order Number & Date | |
| 8 | No of Line item/ Part | |
| 9 | PO Delivery Date | |
| 10 | Project Scope | |
| 11 | Incoterms | |
| 12 | Packing Type | |
| 13 | Tax invoice number & Date | |
| 14 | Actual Delivery date | |

2 Part details- VQ240210_0.B


| | Part details | 3D Image |
|------------------|--------------|---------------|
| Line Item -No | 1 | |
| Item number | | 25.5 |
| Drawing number | VO | |
| Part Description | | |
| Revision number | | II COMPANY |
| Material Grade | AL-600110 | ISOMETIC VIEW |

2.1 MANUFACTURING PROCESS PLAN


| Op No | Process NameS | ymbolSp | ecification | Equipment Selection | Control Mechanism/ Inspection type/Remarks |
|-------|--------------------------------------|---------|---------------------------------|------------------------|--|
| 10 | Raw Material inward Inspection | | AL- 6061 T6 | - | Third party inspection |
| 20 | Band Saw Cutting | | 150 x 225 x 70 | Cutting Machinel | Measuring Tape Inspection |
| 30 | Machining Operation | | As per 2D Drawing | VMC Machine | Vernier Calliper, Height Gauge |
| 40 | Inspection | | As per Balloon Drawing | Manual | Vernier Calliper, Height Gauge |
| 50 | Packing | | As per Agreed Packing method | | Corrugated box |
| 60 | Delivery | | As per Inco terms | Road Transport I | Door Step Delivery |

2.2RAW MATERIAL INSPCTION REPORT

| Inspection Details | | | | | | |
|--------------------|-------------------|--|--|--|--|--|
| Material Grade | AL- 6061 T6 | | | | | |
| Inspection type - | Chemical anaylsis | | | | | |
| Tested at – | Micro Lab | | | | | |
| Report Number - | TRH/24/10247-1 | | | | | |
| Inspected Date - | 14-02-2025 | | | | | |



2.32D DRAWING




2.4FINAL INSPECTION REPORT

| Part /item Number: | VQ240210_0.B | Company Name | EMuski |
|-----------------------|--------------|-----------------|------------|
| Part Name | OBC Housing | Address | |
| Revision Number | F | Inspection Date | 13-02-2025 |

| | Name | Measured value | Nominal value | +Tol | -Tol | Deviation +/- |
|-----|--------------------------|----------------|---------------|--------|---------|---------------|
| | 7.Y Value_Circle4 | -84.2252 | -84.2380 | 0.1000 | -0.1000 | 0.0128 |
| | 8.Y Value_Circle3 | -102.4538 | -102.4690 | 0.1000 | -0.1000 | 0.0152 |
| | 12.X Value_Intersection2 | 14.0392 | 14.0400 | 0.1000 | -0.1000 | -0.0008 |
| | 14.1 X Value_Circle4 | 61.1491 | 61.2000 | 0.1000 | -0.1000 | -0.0509 |
| | 14.2 X Value_Circle3 | 61.1323 | 61.2000 | 0.1000 | -0.1000 | -0.0677 |
| | 16.X Value_Circle8 | 180.1301 | 180.1500 | 0.1000 | -0.1000 | -0.0199 |
| | 18.Y Value_Circle8 | -73.3733 | -73.3500 | 0.1000 | -0.1000 | -0.0233 |
| | 20.Y Value_Circle9 | -48.2249 | -48.2100 | 0.1000 | -0.1000 | -0.0149 |
| | 22.Y Value_Circle5 | -38.5539 | -38.5600 | 0.1000 | -0.1000 | 0.0061 |
| | 23.Y Value_Circle6 | -15.5725 | -15.5700 | 0.1000 | -0.1000 | -0.0025 |
| | 24.Y Value_Circle7 | -9.8221 | -9.8300 | 0.1000 | -0.1000 | 0.0079 |
| | 27.X Value_Circle9 | 180.5126 | 180.5000 | 0.1000 | -0.1000 | 0.0126 |
| | 30.X Value_Circle7 | 122.2101 | 122.2000 | 0.1000 | -0.1000 | 0.0101 |
| | 32.X Value_Circle5 | 91.1967 | 91.2000 | 0.1000 | -0.1000 | -0.0033 |
| | 33.X Value_Circle6 | 90.6946 | 90.7000 | 0.1000 | -0.1000 | -0.0054 |
| | 38.X Value_Intersection1 | 12.9397 | 12.8600 | 0.1000 | -0.1000 | 0.0797 |
| 5 | 39.Diameter_Cylinder1 | 15.9787 | 16.0000 | 0.1000 | -0.1000 | -0.0213 |
| - | 43.Z Value_Symmetry1 | -6.5874 | -6.5000 | 0.1000 | -0.1000 | -0.0874 |
| | 44.C Distance1_X | 44.8423 | 44.8000 | 0.1000 | -0.1000 | 0.0423 |
| ۰ | 45.C Distance1_X | 54.6217 | 54.6000 | 0.1000 | -0.1000 | 0.0217 |
| 0 1 | 46.C Distance1_X | 6.9733 | 7.0000 | 0.1000 | -0.1000 | -0.0267 |
|) | 47.1 Radius1 | 1.5104 | 1.5000 | 0.1000 | -0.1000 | 0.0104 |
|) | 47.2 Radius2 | 1.4850 | 1.5000 | 0.1000 | -0.1000 | -0.0150 |
| | 56.X Value_Circle10 | 170.7365 | 170.7400 | 0.1000 | -0.1000 | -0.0035 |

| Name | Measured value | Nominal value | +ToI | -Tol | Deviation +/- |
|-----------------------|----------------|---------------|--------|---------|----------------|
| 59.Z Value_Point2 | -41.0937 | -41.1000 | 0.1000 | -0.1000 | 0.0063 |
| 60.Z Value_Point1 | -37.6066 | -37.6000 | 0.1000 | -0.1000 | -0.0066 |
| 61.Flatness1 | 0.0069 | 0.0000 | 0.2000 | 0.0000 | 0.0069 🔵 👢 |
| 62.Z Value_Plane7 | -43.5897 | -43.6000 | 0.1000 | -0.1000 | 0.0103 |
| 65.Y Value_Circle11 | -67.3306 | -67.3855 | 0.1000 | -0.1000 | 0.0549 |
| 66.Y Value_Circle15 | -104.3647 | -104.3730 | 0.1000 | -0.1000 | 0.0083 |
| 67.Y Value_Circle1 | -126.3906 | -126.4000 | 0.1000 | -0.1000 | 0.0094 |
| 68.X Value_Circle29 | 36.5584 | 36.5880 | 0.1000 | -0.1000 | -0.0296 |
| 69.X Value_Circle28 | 74.3613 | 74.4030 | 0.1000 | -0.1000 | -0.0417 |
| 70.X Value_Circle11 | 88.9014 | 88.9480 | 0.1000 | -0.1000 | -0.0466 |
| 71.X Value_Circle27 | 134.3930 | 134.4040 | 0.1000 | -0.1000 | -0.0110 |
| 72.X Value_Circle36 | 146.3159 | 146.3520 | 0.1000 | -0.1000 | -0.0361 |
| 73.X Value_Circle35 | 198.6283 | 198.6500 | 0.1000 | -0.1000 | -0.0217 |
| 74.1 X Value_Circle23 | 204.7145 | 204.7450 | 0.1000 | -0.1000 | -0.0305 |
| 74.2 X Value_Circle24 | 204.7362 | 204.7450 | 0.1000 | -0.1000 | -0.0088 |
| 74.3 X Value_Circle25 | 204.7384 | 204.7450 | 0.1000 | -0.1000 | -0.0066 O LILI |
| 74.4 X Value_Circle26 | 204.7333 | 204.7450 | 0.1000 | -0.1000 | -0.0117 |
| 75.1 Y Value_Circle26 | -125.1038 | -125.2000 | 0.1000 | -0.1000 | 0.0962 |
| 75.2 Y Value_Circle27 | -125.1154 | -125.2000 | 0.1000 | -0.1000 | 0.0846 |
| 75.3 Y Value_Circle28 | -125.1555 | -125.2000 | 0.1000 | -0.1000 | 0.0445 |
| 75.4 Y Value_Circle29 | -125.1818 | -125.2000 | 0.1000 | -0.1000 | 0.0182 |
| 76.Y Value_Circle36 | -118.7479 | -118.7950 | 0.1000 | -0.1000 | 0.0471 |
| 77.Y Value_Circle35 | -112.3060 | -112.3690 | 0.1000 | -0.1000 | 0.0630 |
| 78.Y Value_Circle25 | -82.9528 | -82.9990 | 0.1000 | -0.1000 | 0.0462 |
| 79.Y Value_Circle37 | -63.1409 | -63.2000 | 0.2000 | -0.2000 | 0.0591 |
| 80.Y Value_Circle24 | -43.3421 | -43.3990 | 0.1000 | -0.1000 | 0.0569 |
| 81.Y Value_Circle34 | -8.8225 | -8.8640 | 0.1000 | -0.1000 | 0.0415 |
| 82.1 Y Value_Circle20 | 1.7971 | 1.8000 | 0.1000 | -0.1000 | -0.0029 O LILI |
| 82.2 Y Value Circle21 | 1.8321 | 1.8000 | 0.1000 | -0.1000 | 0.0321 |



| Name | Measured value | Nominal value | +Tol | -Tol | Deviation +/- |
|------------------------|----------------|---------------|--------|---------|---------------|
| Y 48.Y Value_Circle7 | -96.9674 | -97.0000 | 0.1500 | -0.1500 | 0.0326 |
| Y 49.1 Y Value_Circle4 | -61.7105 | -61.7000 | 0.1500 | -0.1500 | -0.0105 |
| Y 49.2 Y Value_Circle6 | -61.6675 | -61.7000 | 0.1500 | -0.1500 | 0.0325 |
| Y 50.Y Value_Circle3 | -68.0621 | -68.1000 | 0.1500 | -0.1500 | 0.0379 |
| Y 51.Y Value_Circle5 | -26.3914 | -26.4000 | 0.1000 | -0.1000 | 0.0086 |
| X 52.X Value_Circle6 | -46.8375 | -46.8000 | 0.1500 | -0.1500 | -0.0375 |
| X 53.1 X Value_Circle5 | -82.1201 | -82.1000 | 0.1500 | -0.1500 | -0.0201 |
| X 53.2 X Value_Circle7 | -82.1058 | -82.1000 | 0.1500 | -0.1500 | -0.0058 |
| X 54.X Value_Circle4 | -117.3937 | -117.4000 | 0.1500 | -0.1500 | 0.0063 |
| X 55.X Value_Circle3 | -156.8228 | -156.8000 | 0.2000 | -0.2000 | -0.0228 |

2.5DOCK AUDIT CHECK SHEET

| S. No | ACTIVITY | SPECIFIED | OBSERVATION | | | |
|---------|---------------------------------------|--|-------------|--------|--|--|
| | | | ОК | Value | | |
| 1 | Documents | PDI report with latest drawing revision number | √ | | | |
| 2 | Cleaning | Free from dust stains | √ | | | |
| 3 | Oiling | All surfaces are covered, no excess oil | | | | |
| 4 | Stretch film cover packing | All surfaces are covered with Stretch film | ✓ | | | |
| 5 | VCI bag condition | Free from damage, No oil seepage | ✓ | | | |
| 6 | No. Of parts in each bag/packing | Verify part Qty | | 3 | | |
| 7 | No. Of bags/packing | Verify no of bag /pack Qty | | 1 | | |
| 8 | Sealing of VCI bag with adhesive tape | Free from gaps | √ | | | |
| 9 | Identification Tag | Verify the part no, Description, Qty | √ | | | |
| 10 | Invoice | Verify the invoice as per PO | √ | | | |
| 11 | Whom & When | Verified by & Date of verification | | 15-Feb | | |
| Checked | Checked by : Thiru | | | | | |

2.6 PRODUCT IMAGES





3 KEYLEARNINGS

Key Considerations for Machining Processes - OBC Housing

Pocket ID Depth Machining:

Machining the pocket ID depth is critical, requiring precise control. Tool selection plays a major role in achieving the correct depth while minimizing vibrations that could affect surface quality or tool life.

Vibration Issues: Vibrations during machining, especially at deeper depths, can negatively impact the precision of the pocket and the finish of the part. Proper tool selection and speed/feed adjustments are necessary to minimize this.

Clamping Method: The part must be properly clamped to avoid any movement during machining. If not properly clamped, vibrations from the tool can cause the part to shift, leading to inaccuracies in the depth and finish.

OD Draft Machining:

OD draft machining needs to be ensured for accuracy, with vibrations again posing a risk to the quality of the surface finish. A proper clamping method reduces the risk of displacement during the operation, which can help maintain a consistent angle and taper.

Clamping and Vibration: Inadequate clamping or improper vibration damping could lead to uneven tapering or tool deflection, affecting the overall geometry of the part.

Floor Radius R1:

Maintaining the floor radius (R1) is critical, as an improper radius can affect part performance. Vibrations can cause tool deflection, which will affect the radius and finish.

Tool Failure: Vibration can also accelerate tool wear or lead to tool failure. Effective clamping ensures that the part remains in place, reducing tool wear caused by unintended movement. Process Parameters for Tapping:

Tapping is crucial, and ensuring the correct length of the tap is essential for thread quality and part integrity. Vibrations during tapping can lead to broken taps or poor thread formation.

Vibration Control: Proper clamping during tapping is essential, as any part movement or vibration can lead to misalignment, resulting in incomplete or damaged threads.

Adjusting Parameters: Speed, feed, and cutting depth need to be adjusted based on both tool and part specifications to reduce vibration. This adjustment helps to ensure smooth and accurate tapping.

Clamping Method:

Proper Clamping: Proper clamping is fundamental to ensure the part stays in place during machining operations. Loose clamping can cause vibrations or even displace the part during the process, leading to inaccuracies and defects.

Clamping Considerations: The clamping system should be robust and secure enough to handle the forces generated during machining, especially in processes that involve deeper cuts or tapping.